


SITE NUMBER AND NAME C57 H41:14 Pavement Distress		HIGHWAY & KM km 22	PREVIOUS INSPECTION DATE May 18, 2010	INSPECTION DATE June 19, 2012
LEGAL DESCRIPTION SE18-37-6-W4	NAD 83 COORDINATES N 5780380 E 510040		RISK ASSESMENT PF: 9 CF: 2 TOTAL: 18	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Pavement Distress	
APPROXIMATE DIMENSIONS: About 400 m.	
DATE OF ANY REMEDIAL ACTION:	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		There are several bumps and dips in the pavement.		X
Slope Movement		X			
Erosion		X			
Seepage		X			
Culvert Distress	X		One end of the culvert is damaged and partially blocked.		X

COMMENTS
See attached photos and previous callout report.
The distressed areas should be repaired with deep patches during the next overlay program.
MCI to monitor – remove from geohazard tour.