



S-602

1. Perfect rivet.
2. Stock too long.
3. Stock too short - snap driven on steel.
4. Stock too short.
5. Head not concentric with rivet.
6. Gun not held in line with rivet.
7. Dolly not held in line with rivet.
8. Rivet driven cold.
9. Rivet driven too hot.



S 602

RIVET SAMPLES.

S-602