


SITE NUMBER AND NAME C56 H836:02 Settlement Repair		HIGHWAY & KM km 9	PREVIOUS INSPECTION DATE May 17, 2011	INSPECTION DATE June 14, 2012
LEGAL DESCRIPTION 11-29-23-W4	NAD 83 COORDINATES N 5704031 E 351107	RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1		

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Pavement Settlement – slide on shoulder.	
APPROXIMATE DIMENSIONS: 40 m long	
DATE OF ANY REMEDIAL ACTION: 160 (5 rows) launched soil nails installed in July 2010.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress	X		Cracking along white line at edge of pavement.	X	
Slope Movement		X			
Erosion		X			
Seepage		X			
Culvert Distress		X			

COMMENTS & RECOMMENDATIONS
See attached photos.
The crack should be filled and sealed to prevent water infiltration.
MCI to monitor – remove from Geohazard program.

Site C56 H836
June 14, 2012



Site C56 H836
June 14, 2012

