

**Subject:** Deery #3723 Crack Sealant  
**Location:** Highway 652:02  
**Placed:** July/August 2010  
**Inspected:** February 16, 2011  
**Temperature:** Cloudy, -22C

**Location: Between Range road 130 to 132**



Transverse crack, treated with Deery #3723 sealant



Close-up; very good sidewall adhesion



Crack completely filled, no signs of distress



Material is pliable even at very cold temperature

## Observations

The crack treatment at this test site location was placed in August 2010.

Based on my observations the Deery #3723 crack sealant has provided a very good seal. Sidewall adhesion is excellent at this time and the sealant material seems to be flexible and should perform in cold temperatures. This product is currently listed as a Trial Product on the departments products list until September 2013.

## Recommendations

1. Evaluate the Deery #3723 sealant in the spring of 2011 to determine its performance after one winter.

Joe Filice

cc: Roger Skirrow