

Subject: Deery #3723 Crack Sealant
Location: Highway 881:24
Placed: July/August 2010
Inspected: November 4, 2010

Location: 4.5 Km W. of Gregory Lake Provincial Park



Transverse crack, treated with Deery #3723 sealant



Very good side wall adhesion



Sealant is very pliable

Observations

The crack treatment at this test site location was placed in August 2010.

Based on my observations the Deery #3723 crack sealant has provided a very good seal. Sidewall adhesion is excellent at this time and the sealant material seems to be flexible and should perform in cold temperatures. This product is currently listed as a Trial Product on the departments products list until September 2013.

Recommendations

1. Evaluate the Deery #3723 sealant in the spring of 2011 to determine its performance after one winter.

Joe Filice

cc: Roger Skirrow