

File: 8280-9-7

Steelflex Guardrail Markers


Location: Hwy 619:06

Applied: 2008

Evaluated: September 2012

The 18" Steelflex guardrail markers were installed in Nov. 2008. That makes them 4 years old without any incident or failure. I recommend they get put on the accepted list as a proven and superior product.

Since these were installed, this section of guardrail has not been hit. Prior to the install, this was a problem site with repeated hits. We have saved a lot of money in maintenance costs because of this product.



Hwy 619:06 Test Section 15" Guardrail Reflectors - Highbeam (Note: smaller current reflectors still in place)

Joe Filice

cc: Tom Somerville