

Carsonite Roadmarkers and Curveflex delineators

Installation Date: October 2007

Evaluation Date: January 21, 2010



Carsonite Roadmarkers



Carsonite Curveflex



Damaged Carsonite delineator



Reflective strip torn off the round regular delineator (common Problem)



Top of regular round delineator with top torn off

The Carsonite delineators are performing very well at this location. A small percentage of the Carsonite delineators are damaged, however they are still in place.

The normal round delineator are showing many problems such as; reflective strips torn off or hanging, tops sheared off and post completely sheared off at the base.

The Carsonite delineators will flex above ground level, therefore they will rebound during vehicle impacts. These delineators should out perform the round delineator posts.

Recommend advancing these two products to the Proven Products category.

Joe Filice