

King Block – Guard Rail Spacer Block

Highway 1 at Olds

Installed 2013

Evaluated on January 29, 2014 and April 16, 2014 (after collision)



Side View



Top View



King Block appears to be performing very well at this time. This product is currently listed under the Trail category with an expiry date of November 2016.

Continue to evaluate yearly to determine any defects.

Joe Filice

April 16, 2014 (after collision)



Replaced rail after collision



Post slightly twisted at end (notice tear at bolt location)



End treatment, after collision



Full view of block-out

The King Block – Guardrail Spacer Block seems to be performing well. I am awaiting information from the region regarding the collision and any possible negative effects.

Regional Assessment from Doug Goodine

Requires special crew for repairs

Posts require steaming (4 foot depth) during winter to get them out of ground

Generally repairs take longer than the wood posts.