

Preface to Version 1.1

Technical Standards Branch

BRIDGE INSPECTION AND MAINTENANCE SYSTEM

LEVEL 2 INSPECTION MANUAL

(Release 1.1)

Revisions prepared by:
Reg Quinton, P.Eng.,
Reg Quinton Consulting

and

the Technical Standards Branch Review Committee, consisting of:

Lloyd Atkin, P.Eng.	Bridge Preservation Specialist
Garry Roberts	Senior Bridge Technologist
Clarence Wong, P.Eng.	Bridge Materials Engineer
Ryan Kohlenberg, E.I.T.	Materials Engineering Intern

Printed: March 2007

COPYRIGHT 2007
GOVERNMENT OF THE PROVINCE OF ALBERTA

Version 1.1 of this manual based on Version 1.0 which was prepared by Don Hamilton, P. Eng., CH2M Hill Canada Ltd. The changes in Version 1.1 consist of the addition of Chapter 8 Timber Coring. Chapter 8 Timber Coring was prepared by Reg Quinton, P.Eng., Reg Quinton Consulting and the Technical Standards Branch Review Committee. Chapters 1 to 7 of this manual remain the same as Version 1.0

This page was intentionally left blank

Preface to Version 1.0

Technical Standards Branch

BRIDGE INSPECTION AND MAINTENANCE SYSTEM

LEVEL 2 INSPECTION MANUAL

(Release 1.0)

Prepared by:
Don Hamilton, P.Eng.,
CH2M HILL Canada Ltd.

and

the Technical Standards Branch Review Committee, consisting of:

Tom Loo, P.Eng.	Bridge Preservation Specialist
Ed Kowal, C.E.T.	Bridge Maintenance Technologist
Abdul Waheed, P. Eng.	Bridge Fabrication Standards Specialist
Jennifer Smid, P. Eng.	Bridge Engineer
Paul Carrier, C.E.T.	Bridge Technologist
Holly Will, C.E.T.	Bridge Support Technologist
Gabrielle Moser, E.I.T.	Bridge Intern Engineer

Printed: January 2004

COPYRIGHT 2004
GOVERNMENT OF THE PROVINCE OF ALBERTA

The information contained in this manual was created with assistance on technical issues and editing from the Technical Standards Branch Review Committee. The framework of this manual was based on the previous draft version (0.9) and the Level 1 BIM Inspection Manual (Version 2.0).

This page was intentionally left blank