

DIMENSIONS ARE GIVEN IN mm, DETAILS ARE NOT TO SCALE



REQUIREMENTS AND PROCEDURE FOR SPLICING PIPE PILES

- I. WELDERS SHALL HOLD A CURRENT ALBERTA SECOND CLASS CERTIFICATE OF PROFICIENCY.
- 2. THE LOWER PILE SHALL BE TRIMMED TRUE AND SQUARE.
- 3. THE BEVEL ON THE UPPER PILE SHALL BE FLAME CUT USING A MECHANICAL PIPE BEVELLING MACHINE.
- 4. THE BACKUP PLATE SHALL BE WELDED TO THE UPPER PILE.
- 5. THE UPPER PILE SHALL BE POSITIONED WITH THE BACKUP RING FITTED INTO THE LOWER PILE.
- 6. SPLICE WELD SHALL PENETRATE BACKUP RING. TWO PASSES ARE REQUIRED IF THE PILE WALL IS GREATER THAN 8 mm. GRIND WELD SMOOTH IF THE SPLICE IS LOCATED ABOVE GROUND LEVEL.
- 7. WHEN THE AIR TEMPERATURE IS BELOW O°C, ALL MATERIAL TO BE WELDED SHALL BE PREHEATED TO 100°C FOR A DISTANCE OF 80 mm BEYOND THE WELD AND SHALL BE SHELTERED FROM THE WIND.
- 8. WHEN THE AIR TEMPERATURE IS BELOW -20°C, WELDING WILL NOT BE PERMITTED UNLESS SUITABLE HOARDING, APPROVED BY THE ENGINEER, IS PROVIDED,

DRAFTING STANDARDS PAGE: 3.7

(5)

A						Abouto		DRTATION		UTILITIES
A	99-03	-29 E	BEB CHANGED T	O TSB	RY	MILCHIC	TECHNIC	AL STAN	DARDS	BRANCH
A	94-11	-30	GENERAL NOTES		RJR	STANDARD				
\triangle	87-03	-09 F	REDRAWN FROM S-1414 REVISIONS		DHQ	טיטי				
NO	DAT	Ε			BY	PIP	- PILE	SPLICE		
	IGNED HQ	DRAWN		APPROVED EXECUTIVE DIRECTOR	1	SIGNATURE	DATE My 8/87	PAGE 3.15	S-14	awing 414-87