


NOTES:


1. ELEVATIONS RELATIVE TO ASSUMED BENCHMARK ELEVATION OF 100 m
2. CONTOUR INTERVAL 0.5 m



JUNE 2010: CABLES
BROKEN OR BRAKE
ELEMENTS ACTIVATED

JUNE 2010
ANCHOR ROPES AND
CABLES DETACHED AND/OR
INSUFFICIENTLY TENSIONED.
SEE TEXT FOR DETAILS.

SCALE



CLIENT:

Alberta Transportation

PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT

TITLE: S15 - CROWSNEST LAKE ROCKFALL BARRIER

DATE: OCTOBER 2010	JOB No.: CG25332.200	CAD FILE: 25332B02.dwg	FIGURE No.: FIG S15-1	REV. A
-----------------------	-------------------------	---------------------------	--------------------------	-----------