


JUNE 2007 – APPROXIMATE LOCATION OF NEW CRACK IN ROAD, OUTSIDE OF APPARENT EAST FLANK OF LANDSLIDE



PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT AND INSTRUMENTATION MONITORING				
TITLE: SUMMARY OF INTERPRETATION OF DATA FROM FUNCTIONING INSTRUMENTS HWY 22:14 PRIDDIS SLIDE AREA				
DATE: SEPTEMBER 2011	JOB No.: CG25352.200	CAD FILE: 25352N03.dwg	FIGURE No.: FIGURE S2-1	REV. A

CLIENT: