


Overlays of various ages.
Typical pattern and extent of
cracking shown.



Client	Alberta Transportation		Figure S10(C)-1	
Project	Southern Region Geohazard Assessment		Date:	Revision
			Sep-11	
			Job No.	
			CG25352.200	
			File No.:	
S10(C) - HIGHWAY 762:02				

