





- NOTES:**
1. ELEVATIONS RELATIVE TO ASSUMED BENCHMARK ELEVATION OF 100 m
 2. CONTOUR INTERVAL 0.5 m



	PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT AND INSTRUMENTATION MONITORING			
	TITLE: S15 - CROWSNEST LAKE ROCKFALL BARRIER			
CLIENT: Alberta Transportation	DATE: SEPTEMBER 2011	JOB No.: CG25352.200	CAD FILE: 25352B02.dwg	FIGURE No.: FIG S15-1
				REV. A