



**Photo 1 (May 2013) –**  
Standing at the creek bank  
at the east end of the East  
Site, looking towards the  
southwest at the bank  
erosion.



**Photo 2 (May 2013) –**  
Standing on the bank at the  
west end of the West Site,  
looking towards the east at  
the bank erosion.



**Photo 3 (May 2013) –**  
Standing at the West Site  
looking towards the  
northeast at the backslope  
sliding.