

SUMMARY OF SITE INSTRUMENTATION:

## CENTRAL REGION LANDSLIDE RISK ASSESMENT SITE INSPECTION FORM



INSPECTED BY:

SITE NUMBER AND NAME HIGHWAY & KM			1	PREVIOUS			INSPECTION DATE			
C22 H22:20 Pavement Dips				INSPECTION DATE May 28. 2002			May 23, 2003			
			IVIAY 20, 2002			<b>y</b> =0, =000				
LEGAL DESCRIPTION	NAD 83 COO	RDINATES	RISK	( ASS	ESMEN	Т				
	N 5761985	E 660135	PF:	9	CF:	4	TOTAL:	36		

None	OF ESSOL	ENGINETA PARTIES OF ALBERT									
LAST READING DATE:											
PRIMARY SITE ISSUE:  Pavement Settlement  APPROXIMATE DIMENSIONS:											
DATE OF ANY REMEDIAL ACTION:											
ITEM CONDITION EXISTS		STS	DESCRIPTION AND LOCATION			NOTICABLE CHANGE FROM LAST INSPECTION					
	YES	NO			YES	NO					
Pavement Distress	Х		Settlement at two locations about 100 m apar	T		Х					
Slope Movement											
Erosion											
Seepage											
Culvert Distress											
COMMENTS											
Refer to previous reports											
Site investigation to be undertaken in July 2003											
Refer to attached photos											