



Photo 1 (top) – June 2009

Facing westbound across the wall face, showing the relative position of the highway, wall and steep slope below the wall.



Photo 2 (bottom) – June 2009

Closer view, facing westbound, across the wall face below the highway.



Photo 3 – June 2009

Facing down from the crest of the wall, towards some of the erosion gullies in the slope below the wall. Note the position of the Highwood River channel visible in the right background.