



Photo 1 – Looking northeast at west crack, June 5, 2006



Photo 2 – Looking northeast at east crack, June 5, 2006



Photo 3 – Looking east along north guardrail, June 5, 2006



Photo 4 – Looking east along north guardrail (west of Photo 3), June 5, 2006



Photo 5 – Subdrains and culvert outlet near Sta. 1+680, June 5, 2006



Photo 6 – Looking west at tension cracks in trail above binwall, June 5, 2006



Photo 7 – Closer view of new crack to south of existing cracks, June 5, 2006



Photo 8 – Closer view of new crack to west of existing cracks, June 5, 2006



Photo 9 – Looking west at bin wall (Sta. 1+200), June 5, 2006



Photo 10 – Looking east at bin wall (Sta. 1+200), June 5, 2006