



Photo 1 - Looking northeast at west crack.

May 31, 2005



Photo 2 – Looking northeast at east crack.

May 31, 2005



Photo 3 - Looking east along north guardrail.

May 31, 2005



Photo 4 – Looking west along north shoulder.

May 31, 2005



Photo 5 – Subdrains and culvert outlet near Station 1+680 (south of highway).



Photo 6 – Sinkholes above culvert outlet at Station 1+680 (looking south).
Photos taken May 31, 2005



Photo 7 – Tension crack in paved trail southwest of bin wall (looking west).



Photo 8 – Tension crack in paved trail southwest of bin wall. May 31, 2005



Photo 9 – Bin wall Station 1+200 looking west.

May 31, 2005



Photo 10 – Bin wall Station 1+200 looking northeast.

May 31, 2005