



**Photo 1:** Repaired sideslope requires topsoil and seeding



**Photo 2:** Looking west along Access Road 172; cracks present along roadway