



Photo 1: Whitemud River Station 42+600, repaired slope, minor clean up remaining to be done, May 2003



Photo 2: Whitemud River Station 42+600, repaired culvert outlet, minor erosion to be repaired, May 2003



Photo 3: Whitemud River Station 42+650, scarp, May 2003



Photo 4: Whitemud River Station 42+750, scarp, May 2003



Photo 5: Whitemud River Station 42+750, slope movement, May 2003



Photo 6: Whitemud River Station 44+000, sinkhole at culvert crossing, May 2003



Photo 7: Whitemud River, Station 44+000, erosion downstream of culvert crossing, May 2003



Photo 8: Whitemud River Station 44+000, erosion at culvert outlet, gabions left, shale bedrock right, May 2003



Photo 9: Whitemud River Station 45+800, slumping at culvert outlet, May 2003