



PHOTO 1: Sta. 43+200, Shale backslope looking in the SE direction



PHOTO 2: Sta. 43+200, Shale backslope and the debris pile



PHOTO 3: Sta. 43+200, Shallow erosion gully on the highway sideslope



PHOTO 4: Sta. 43+200, Highway sideslope



PHOTO 5: Sta. 42+600, NW highway sideslope



PHOTO 6: Sta. 42+600, Culvert outlet and gabion walls



PHOTO 7: Sta. 42+600, Repaired Slope and culvert inlet