



Photo 1 – Reconstructed slope at Station 42+600, June 16, 2006.



Photo 2 – Creek channel below repaired slope at Station 42+600, June 16, 2006.



Photo 3 – Shallow slides in cut slope in the west side of highway at Station 42+600, June 16, 2006.



Photo 4 – Culvert outlet at Station 42+600, June 16, 2006.



Photo 5 – Shallow slides in highway west fill slope above culvert at Station 42+600, June 16, 2006.



Photo 6 – Looking south at slide area on west side of highway at Station 42+600, June 16, 2006.



Photo 7 – Looking north at slide area on west side of highway at Station 42+600.



Photo 8 – Shale Slope at Station 43+200, June 16, 2006.



Photo 9 – Shale Slope at Station 43+200, June 16, 2006.