



Photo 1.
Slide 1 at the north end of the site. No fresh slide movement.



Photo 2.
Looking down slope (eastwards) at Slide 1. No significant changes since 2007. Note the water in the sag pond above the Heart River.



Photo 3.
Looking south along the backscarp of Slide 2. There is fresh movement in the backscarp, and erosion due to water draining from the ditch. The vertical offset at the indistinct backscarp south of this slide (arrow) appears to have increased.



Photo 4.
North end of Slide 2. There may be some fresh movement at this end of the slide, though there is some grass take on the debris at this end of the slide bowl.



Photo 5.
Looking southwards
across the backscarp
of Slide 3. No fresh
movement.



Photo 6.
Further significant
slide movement in
the backscarp of
Slide 4. Note the
bands of wet soil in
the backscarp.



Photo 7.
Slide runout for Slide 4. Note the steep, high flanks of the slide bowl.