


KEY PLAN

JUNE 2007 - APPROXIMATE LOCATION OF NEW CRACK IN ROAD, OUTSIDE OF APPARENT EAST FLANK OF LANDSLIDE



PROJECT:	SOUTHERN REGION GEOHAZARD ASSESSMENT AND INSTRUMENTATION MONITORING			
TITLE:	SUMMARY OF INTERPRETATION OF DATA FROM FUNCTIONING INSTRUMENTS HWY 22:14 PRIDDIS SLIDE AREA			
DATE:	JOB No.:	CAD FILE:	FIGURE No.:	REV.
OCTOBER 2010	CG25332.200	25332N04.dwg	FIGURE S2-1	A

CLIENT: