


JUNE 2007 – APPROXIMATE LOCATION OF NEW CRACK IN ROAD, OUTSIDE OF APPARENT EAST FLANK OF LANDSLIDE



PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT				
2012 ANNUAL INSPECTION				
TITLE: SUMMARY OF INTERPRETATION OF DATA				
FROM FUNCTIONING INSTRUMENTS				
HWY 22:14 PRIDDIS SLIDE AREA				
DATE:	JOB No.:	CAD FILE:	FIGURE No.:	REV.
NOVEMBER 2012	CG25399.200	25399D07.dwg	FIGURE S2-1	A

