



Photo 1 – Facing north across the slide scarp, central portion (May 2002).



Photo 2 – Facing north across the slide scarp, central portion (May 2001).



Photo 3 – Facing south across the slide scarp, central portion (May 30, 2002).



Photo 4 – Point of maximum crest retrogression, May 1, 2002 (adjacent to SI #8). There is a buried Telus line parallel to, and to the left of, the fence.



Photo 5 – Facing south towards tension cracks that delineate a new slide block developing on north flank of overall slide. SI #10 in background. (Photo from May 1, 2002).



Photo 6 – Facing north from SI #10 towards new slide block developing on north flank of overall slide. (Photo from May 30, 2002).



(May 2002)

Photo 7 – Facing south across slide area. Note river erosion at toe of slide.



(May 2002)

Photo 8 – Close-up of toe of central portion of slide, partially protected from direct erosion by island in creek. Note oversteepened portions of toe slope.