Alberta Infrastructure and Transportation Southern Region Geohazard Assessment Annual Assessment Report CG25263 September 2007








Photo S4-1 – June 2007 (top)

Facing north across the landslide area. The extent of the slope crest retrogression past the fenceline and towards the northbound lanes of Highway 2 is visible.



Photo S4-2 – June 2007 (bottom)

Facing south across the landslide area. The current offset between the crest of the slope in the landslide area and the northbound lanes of Highway 2 is visible.