



Photo S8-1 – June 2008 (top)

Facing southbound across the northern end of the S8 – Fisher Creek site. The arc-shaped settlement and cracking in the right foreground corresponds to the “Northern Cracking and Settlement Area” labelled on the site plan. The overlay visible over this area is typically re-done annually to maintain a smooth grade along the west shoulder, however the accumulated thickness of the overlays has created a steep drop-off from the edge of the pavement.



Photo S8-2 – June 2008 (bottom)

Facing northbound across the area shown in Photo S8-1.



Photo S8-3 – June 2008 (top)

General view facing southbound across the south end of the site. The SI's in this area are showing ongoing movement underlying the road, however there has been little to negligible damage to the road surface across the southern end of the site.