

Photo 5 –Site C looking Southwest.



Photo 6 –Site C – Showing dip in highway.



Alberta Transportation Southern Region Landslide Monitoring Program Spring 2001 Assessment Report

Site S10 – Highway 762 Miscellaneous Sites



Photo 7 –Site C – Downstream (east) side of embankment (looking north).



Alberta Transportation
Southern Region Landslide Monitoring Program
Spring 2001 Assessment Report

Site S10 – Highway 762 Miscellaneous Sites