



Photo 9 – Site C – facing north (May 2002).



Photo 10 – Site C - facing south across area repaved in October 2001. Note crack forming parallel to west shoulder. May 2002 photo.