





- NOTES:
1. ELEVATIONS RELATIVE TO ASSUMED BENCHMARK ELEVATION OF 100 m
 2. CONTOUR INTERVAL 0.5 m



JUNE 2008
 ANCHOR ROPES AND
 CABLES DETACHED
 AND/OR INSUFFICIENTLY
 TENSIONED.
 SEE TEXT FOR DETAILS.



 CLIENT:	PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT			
	TITLE: S15 - CROWNEST LAKE ROCKFALL BARRIER HIGHWAY 3:02			
	DATE:	JOB No.:	CAD FILE:	FIGURE No.:
	AUGUST 2008	CG25277.B		FIG S15-1
				REV. A