



AIR PHOTO REFERENCE: JUNE 2005, GOVERNMENT OF ALBERTA, 05-164, 82I, LN-27, AS5333B #249, 1:10 000

NOTE: RIVER IN FLOOD CONDITION AT TIME OF PHOTO.



		PROJECT: SOUTHERN REGION GEOHAZARD ASSESSMENT 2012 ANNUAL INSPECTION			
		TITLE: SITE LOCATION, HIGHWAY 56 S32 - BOW RIVER UPSTREAM OF CROWFOOT FERRY			
CLIENT:		DATE: NOVEMBER 2012	JOB No.: CG25399.200	CAD FILE: 25399D08.dwg	FIGURE No.: FIGURE S32-1 REV. A



Notes:

1. All dimensions approximate and based on June 2012 inspection.

Client	Alberta Transportation		Figure S32-2	
Project	Southern Region Geohazard Assessment		Date:	Revision
S32 - BOW RIVER UPSTREAM OF CROWFOOT FERRY HIGHWAY 56 SCHEMATIC SITE PLAN EAST FERRY RAMP			Nov-12	
			Job No.	
			CG25399.200	
			File No.:	
			S32 Figures.xlsx	

