



**Photo 1** – Summer 2006 rockfall event originating from the upper slopes of Mount Rundle above Highway 742:02, between approximately Km 4.5 and Km 5.0 along the highway. It is understood that several boulder-sized rocks were deposited on the road surface during this event.  
(Photo provided to AMEC by the Parks Division.)