Alberta Transportation Southern Region Geohazard Assessment Highway 940, Wilkinson Creek Bridge Area CG25309.B August 2009

Floodplain on

highway






Photo 1 - June10, 2009 (top) Facing northbound along Highway 940 and downstream along Wilkinson Creek.

Small levee along left bank, prone to overtopping during peak flows

Alberta Transportation Southern Region Geohazard Assessment Highway 940, Wilkinson Creek Bridge Area CG25309.B August 2009





Photo 2 – June10, 2009 (top)
Facing southbound along
Highway 940 from the bridge
location, and also facing upstream
along the Wilkinson Creek channel
(visible in the left background)