



LEGEND

- Area of cracking / settlement
- Slope Inclinometers ◆
- VW Piezometers ▼
- Noted Cracking / Scarps

SCALE AND ALL MARKED FEATURE LOCATIONS ARE APPROXIMATE

Client	Alberta Transportation	Figure S38-1	
Project	S38 - Hwy 22:08 - Callum Creek	Date: Nov-12	Revision:
Site Plan and Location		Job No.:	
		CG25399.300	
		File No.:	
		Figure_S38-1.xls	

