



Photo S40-1 – May 2013
Standing south of the highway looking at the apparent recent collapse of a sinkhole observed around the area marked by WPT 60 on the site plan.



Photo S40-2 – May 2013
Standing at the north highway edge looking towards a collapsed sinkhole that has eroded a vertical face up to the road. A tunnel appears to be connected that runs beneath the highway located at WPT 105.



Photo S40-3 – May 2013
Standing on the southeast
road shoulder looking
towards the east at the
south ditch erosion.