



Photo S41-1 – June 22, 2012

Facing east towards the site from across the valley. Well-developed landslide topography is visible below the highway. The headscarp is marked in the photograph.



Photo S41-2 – June 22, 2012

Facing southwest from the old guardrail position, looking towards the closed southbound lane and area of settlement within the now closed road surface.



Photo S41-3 – June 22, 2012

Facing northeast on the upslope side of the road near the south end of the site. No cracking in the upslope highway lane was observed.