



Photo 1: Whitemud River, culvert outlet, 2000



Photo 2: Whitemud River, culvert outlet, 2001



Photo 3: Whitemud River, culvert outlet erosion of gabions, 2002