



Photo 1: Judah Hill, Slide # 1 in Zone D1, settlement and cracks in pavement, May 2002.



Photo 2: Judah Hill, north of Zone D2, steep slope downhill of slide, debris flow scar and slide at base of slope, May 2002.



Photo 3: Judah Hill, north of Zone D2, steep slope downhill of slide and debris slide scar, May 2002.



Photo 4: Judah Hill, north of Zone D2, settlement and cracks in pavement, May 2002.



Photo 5: Judah Hill, north of Zone D2, settlement and cracks in pavement, May 2002.



Photo 6: Judah Hill, Zone B1, settlement and cracks in pavement, October 2002.