

CENTRAL REGION GEOHAZARD RISK ASSESMENT SITE INSPECTION FORM



SITE NUMBER AND NAME		HIGHWAY & KM	PREV	IOUS		INSP	ECTION DAT	E	
C44 H760:02 Slide			INSPI	ECTION	N DATE		una 26 2	nno	
C44 H/60.02 Slide	3			Oct 29, 2007		June 26, 2008			
LEGAL DESCRIPTION	NAD 83 COOF	RDINATES	RISK	(ASS	ESMEN'	T			
NE 19-48-5-W4	N 5890109	E 519390	PF:	1	CF:	1	TOTAL:	1	

SUMMARY OF SITE INSTRUMENTATION:		INSPECTED BY:		
		ENGINE		
None		N. RA		
LAST READING DATE:		Υ,		
PRIMARY SITE ISSUE:				
	Slope Failure			
APPROXIMATE DIMENSIONS:				
DATE OF ANY REMEDIAL ACTION:	Slide area excavated and reinstated with rein	forced gravel August 2007.		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION		NOTICABLE CHANGE FROM LAST INSPECTION	
	YES NO				NO	
Pavement Distress		Χ	Pavement patched since last inspection.	X		
Slope Movement		Χ	Stabilized slope is performing well. No evidence of slope movement is apparent.		Х	
Erosion		Χ			Х	
Seepage		Х			Х	
Culvert Distress		Х			Х	
COMMENTS						
Refer to attached phot	tos and	previo	us reports.			



Page 1 of 2



Page 2 of 2