


SITE NUMBER AND NAME C51 H841:02 Erosion		HIGHWAY & KM	PREVIOUS INSPECTION DATE June 18, 2007	INSPECTION DATE June 13, 2008
LEGAL DESCRIPTION NE 29-27-20-W4	NAD 83 COORDINATES N 5689106 E 377410		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Ditch erosion, embankment slide	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Ditch erosion infilled with gravel summer 2007. Embankment slide trimmed by maintenance contractor since previous inspection.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement	X		No slope movement is apparent since trimming.	X	
Erosion	X		Erosion had cut into highway edge; channel was filled with gravel but erosion continued. Additional gravel was added to channel and erosion does not appear to have progressed further.	X	
Seepage		X			X
Culvert Distress		X			X

COMMENTS
Refer to attached photos.

Site C51 H841:02 Erosion
June 13, 2008



Site C51 H841:02 Erosion
June 13, 2008

