

CENTRAL REGION GEOHAZARD RISK ASSESSMENT SITE INSPECTION FORM



**INSPECTED BY:** 

Transportation

SITE NUMBER AND NAME	HIGHWAY	-	REVIO		INSPECTION	N DATE
C59 H841:02 Slide	& KM		ECTION	NDATE 2013	June	6, 2014
LEGAL DESCRIPTION	NAD 83 COORDINATES	RISK ASSESMEN			Г	
		PF:	9	CF: 4	TOTAL:	36

SUMMARY OF SITE INSTRUMENTATION: None

LAST READING DATE:

PRIMARY SITE ISSUE: Embankment Slide

APPROXIMATE DIMENSIONS:

DATE OF ANY REMEDIAL ACTION: 2010, 2012, and 2013

ITEM CONDIT EXIST			DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION YES NO						
Pavement Distress		X	Gravel road							
Slope Movement	Х		Surficial slide in poor quality fill on slope	Х						
Erosion		Х								
Seepage	Х				Х					
Culvert Distress		Х			X					
COMMENTS										
See Callout and Construction Reports										







