

**Slide Name:** (GP 19) SH 677:02 W. of Woking and E. of SH 731:02  
**Inspection Date:** N/A  
**Inspection By:** N/A

## **1.0 BACKGROUND**

Refer to EBA 2001 and earlier reports for site conditions and details of risk assessment.

## **2.0 OBSERVATIONS**

- This site was not inspected during the 2003 and 2004 tour.
- It was reported by AT staff that a new culvert installation and pavement construction were carried out in 2003 for the roadway.

## **3.0 RISK ASSESSMENT**

PF (5) \* CF (2) = 10


Risk rating cannot be changed from that assessed in 2000.

## **4.0 ACTION**

- Visual monitoring of this site should be continued.
- The site should be inspected in year 2005.



Based on 1995 Aerial Photograph



**Figure 1**  
Site Plan