

**Deery 101 ELT Sealant
Rout and Seal
Highway 16 (WBL to hwy 43 turn off)
Sealant was applied in 2003**

File: 8085-4-16
February , 2006



Transverse crack



Close-up



Sealant in good shape; small amount of sidewall adhesion problems.



Close-up



Sealant is performing very well



Sidewall adhesion failure

Summary

The Deery 101 ELT sealant was observed on the afternoon of February 13, 2006 by J. Filice. The Deery 101 ELT sealant placed in the transverse cracks is performing very well on this highway. I would estimate that there is less than 5% sidewall adhesion failure on the transverse cracks.

The Deery 101 ELT sealant is performing very well on this project. This product is presently on the Trial Products category of the AIT products list expiring in June 2006. Based on this assessment I would recommend this product be advanced to the Proven Products category.

Joe Filice
Cc: Roger Skirrow